

Screen Kit Installation Triumph Sprint ST/GT 1050.

The first step is to mark the position of the 4 holes to mount the adjustable brackets, as shown below.




Once marked up, double check the hole positions are symmetrical and correctly spaced.

Then, using a 6mm bit, carefully drill the holes to avoid cracking the screen.

This operation is ideally carried out with the screen still attached to the fairing as it's held rigidly in position.



With the holes drilled, remove the masking tape and clean up the screen prior to mounting the brackets.



Using the fasteners provided, mount the brackets (ensuring a washer is placed between the brackets and the screen to help isolate stress and scratches) and secure underneath using the plastic washers and lock-nuts - do not overtighten or this may crack the screen.



With the brackets mounted, check they are perpendicular and parallel before mounting the screen.

When mounting the screen, ensure thye rubber washers are fitted between the bracket tabs and screen (as shown below) as these help reduce stress on the screen - again, do not overtighten.



If you have selected the optional Accessory Bar, simply attach onto the existing bracket holes as shown below.

Once you have double checked all the fasteners for security, you are now ready for a test ride.

We recommend you set the screen so that you can see over the top and a point on the ground about 6 feet in front of the bike, with the screen set on the middle tilt setting.

Do not attempt to make adjustments whilst riding and regularly check the tightness of the tool-less adjusters (if selected).

END